



Temp Products

Tech Tip

Hyundai Water Pump: NAPA Round Hub with Locator Pin Replaces Square Mounting Hub

The water pump on some Hyundai cars has a square mounting hub, while the NAPA replacement water pump has a round hub.

- The 1996-02 Hyundai Elantra and Tiburion, with a 1.8L or 2.0L 4-cylinder engine, have water pumps that have one of two different shaped mounting hubs on the water pump for the pulley to attach.
- Even though one is round and the other square, the mounting holes are spaced the same.
- The round hub uses a locator pin on the flange and the square hub uses a locator “knob” on the shaft.
- NAPA replacement part number 41061 has a round hub with a locator pin. When using an OE equivalent water pump pulley, this part number is the correct part for this application.

**NOTE WHICH DIRECTION
THE PULLEY IS FACING
BEFORE REMOVING IT FROM
THE WATER PUMP. FAILURE
TO INSTALL THE PULLEY
CORRECTLY WILL CAUSE
SEVERE BELT MISALIGNMENT.**

