

**BULLETIN PA003-11****PART NUMBER:**

38379K

MAKE:Chrysler
Dodge
Plymouth**MODEL:**Caravan
Grand Caravan
Town and Country
Voyager
Grand Voyager**YEAR:**

1996-2000

ENGINE:3.3L
3.8L**SOLUTION KIT 38379K - CHRYSLER CORP.**

NAPA Belts/Hoses Drive Kit 38379K was designed to prevent the Micro-V belt from being thrown off in rain or snow driving conditions. This was a problem among 1996-2000 Chrysler Minivan applications and NAPA Belts/Hoses has the only true solution to the problem. This Drive Belt Kit was field tested on a fleet of new vehicles in rain and snow conditions. The results were superior without one failure during the testing period.

As the age of these applications gets older, there have been field reports that there is an installation issue with the Dual Sided Micro-V belt included in the kit when other components have been replaced in the drive system. After extensive research was done, it was found that in these instances either a power steering pulley and/or the Air Conditioner have been replaced on these systems. The replacement parts used for the installations are not dimensionally the same as Original Equipment. Should you encounter a problem with the belt being too short for installation, NAPA Belts/Hoses DriveAlign Pulley part number 38008 is available to correct the problem. By using this pulley which is 6 mm smaller than the one provided in the kit you are able to install the belt and have proper operation of the belt drive system.



38009 = 76mm O.C. Provided in kit



38008 = 70mm O.C. Use if belt length issues are encountered due to other aftermarket accessory replacement components.

Always check that the tensioner is in the proper operating range after repairs.



** The NAPA Belts/Hoses Dual Sided Micro-V Belt provided in the kit is designed to operate on the smooth pulley attached to the water pump.